

MESAS Quality management systems do not only provide a

variety of Vers.ard functions

capable to solve most problems of

quality management, but also a

yourself. And if this is even not

programming and application

engineers will elaborate your

and software system provider.

number of flexible tools enabling

you to create special solutions by

enough, our team of highly qualified

individual solution. Take the chance

to profit by our expertise as a hard-

## MESAS MQMD Software

- MESAS MQMD Software for Microsoft Windows® is the innovative consecution of MESAS Software operating successfully on DOS® systems for over 10 years. Traditionally easy handling due to transparent menu structure

  - online assistance
  - catalogue functions
- Centralized or decentralized data management
- interfaces to existing MESAS SPC systems operating under DOS®
- Data export to external software like Q-DAS gs-STAT or Microsoft Excel
- Open Client/Server architecture
- Static and dynamic measuring routines
- Easy programming editor for assignment of measuring inputs to their respective characteristics, for definition of mathematical or logical relations between measuring inputs, for measurement control and operator instruction
- **Tool correction programming**
- Drivers for various types of measuring equipment (transducers digital measuring equipment, incremental probes, pneumatic probes, digital measuring equipment etc.)
- Comprehensive reporting system for quality documentation - adoptable to your requirements
- Planning and realization of your Quality **Management Network**




1/7



# **Check list specification and management**

- For simple check lists or complex applications
- Flexible programming of measuring control for static and dynamic measuring tasks



2/7



### **MQMD** Measuring

The software can be operated by means of a Vers.ard ASCII-keyboard or by the industrial MESAS operator panel.

#### Measurement displays

- Column display
- Part picture
- Alpha-numerical listing
- chronol. listing of individual measurements
- Quality Control Charts
- Multiple Quality Control Charts
- or combinations of the above displays

Measurement results are coloured differently depending on their quality:

G: OK N: Rework A: Scrap


W: Violation of warning limits


The sample result shows up automatically at the end of a sample.

Online messages indicate special events like Run, Trend, Middle Third

Ongoing calculation of control limits and capability indices (cp, cpk)

The display on the right shows a combination of alphanumeric listing with column display and zoomed value of the selected characteristic.










The displays can be combined individually. The display on the right shows a combination of columns, alphanumeric listing and quality control chart.


# **MESAS MQMD Software**



### Quality control charts for online evaluation of the production process

- Vers.ard Xbar-/ S-chart with histogram based on the last 25 samples
- Xbar-/ S-chart based on alternating groups of samples
- Xbar-/ R-chart over the last 25 samples
- Xbar-/ Rr-Karte (moving range) over the last 100 measurements
- C-chart for attribute characteristics
- Individuals chart over the last 100 measurements

Action flags can be added to the quality control chart to mark special events like tool change, faulty measurement etc.




X-bar/s-chart with action flag (sample 3)

#### Multi-QCC:

- up to 4 quality control charts or
- up to 9 x-bar charts

Displayed on the screen at the same time.





# **MQMD Long Term Evaluation**

MQMD Long Term Evaluation is a program for statistical evaluation, visualisation and reporting of measuring data gathered by MESAS MQMD for Windows and MESAS SPC for DOS.

Evaluation based on IATF 16949 or customer request:

- Preliminary process capability
- Process capability
- Measurement evaluation

Automatic or manual selection of distribution check method: e.g. Normal-, Log-Normal-, Weibull, Rayleigh-, Folded distribution etc.


- Filter criteria for selection of measurements: parts, characteristics, evaluation period, serial numbers, operators, machines etc.
- Choice of indices for variation and position
- Choice of quality control charts
- Calculation of control limits and process capability indices
- Automatic elimination of outfliers
- Facility to highlight and/or exclude individual samples from evaluation





Diagrams on screen and printer

Pareto Analysis	Share of faulty characteristics
Histogram	Variable number of classes
Attribute chart	Fault index p/np or cu for attribute characteristics
Sample chart	Alphanumeric listing of samples
Multi-individuals-chart	Individuals chart for several characteristics in one diagram
Vers.ard quality control chart	Xbar- / s-chart or X-bar- / R-chart
Multi- quality control chart	4-12 quality control charts on the screen at the same time
Moving quality control chart	Calculations are not based on fixed samples but on
	alternating groups of samples
Serial numbers	Simple individuals chart with serial number and operator
Overview	Up to 15 characteristics with alphanumeric information and
	histogram



### **MQMD Master Data**

Master data are global, program wide data, which are not subject to many changes, once they have been entered (e.g. parts- and characteristics data, suppliers, machines etc.). Master data are the base for catalogue assisted working with check lists and inspection orders.






Defining master data is useful, if you intend to centralize and evaluate your quality data within a superior or company-wide system (e.g. quality network).

The catalogisation and uniqueness of the master data allow an unambiguous assignment of the collected inspection data.

The master data management software provides a variety of catalogue criteria. Which ones you actually use, is depending on your company requirements.

# **Special Solutions**

- On screen visualisation for operator guidance
- Classification
- Dynamic gear checks
- Fast Fourrier (FFT)
- Roundness check (MZC)
- Camber and ovality check (BOP)





7/7